

FAX

ATTN. Maja Stevanovic

Fax Number 14802474354

Phone Number

FROM Richard Olson

Fax Number 507-332-7152

Phone Number 952-920-1360

SUBJECT

Number of Pages 13

Date 9/16/2008

MESSAGE

Truth in Sale of Housing Disclosure Report

NOTICE - Read Entire Report Carefully. This is not a Buyer's Inspection!

Address: 5374 Shoreview Ave Minneapolis, MN



Current Owner Name: Branko Kastratovich

Contact: Branko Kastratovich

Business/Relationship:

Owner Address: 6528 Sherwood Ave.
Edina, MN 55435

Home Phone: 000-000-0000

I declare to the best of my knowledge the following information:
 This property has had environmental testing, removal, or remediation of environmental contamination by the United States Environmental Protection Agency, Minnesota Pollution Control Agency, other governmental agency, or under the direction of such agency: Yes / No
 If yes, the seller shall provide the testing, removal, or remediation results to the buyer.
Water Damage to Property: flood damage sewer backup water seepage
 Please Describe:

Age of Roof: _____ **Condition of Roof:** Poor Fair Good Excellent **Currently Leaking:** Yes / No **Patched:** Yes / No
Signature of Owner: (Report Not Valid Without Signature) **Date:**

***** SEE ATTACHED PAGES FOR IMPORTANT CONSUMER INFORMATION *****

THERE ARE REQUIRED REPAIR/REPLACE ITEMS NOTED IN THIS REPORT.

Observed Number of Units: 1

City Reference as: 1

Building Type: Single Family Home

Present Occupancy: Conforming

Zoning: R1 - Single Family District('99)

Housing Orders: No

Condemnation Status: NA

Reason: NA

1. This report offers a limited overview of the building components and fixtures and is not technically extensive. Prospective buyers may want to seek additional opinions from various experts in the inspections field prior to purchase. This report is not a warranty or guarantee, expressed or implied, by the City of Minneapolis or by the evaluator or of any building component or fixture. Further, the buyer may want to seek additional information regarding any open permits. For 1st time condominium units, this report includes only those items located within the residential units. The Professional Opinion covers those items in the common areas of the building.
2. The buyer must repair all items marked Repair/Replace, unless the seller agrees to do the repairs. The seller is not required to complete the RR's if the property does not sell. All required Repair/Replace items are enforceable by Minneapolis Ordinance Chapter 248 and/or 250. All other items will not be used by the Inspections Division as a basis for enforcing Minneapolis ordinances.
3. The ordinance requires that no person shall exhibit or show a dwelling for sale without first having obtained an official Evaluation Report and places the responsibility on the seller or agent to make sure that this report (and in the case of 1st time condo conversions, the Professional Opinion,) is publicly displayed on the premises at all times when the house is shown to prospective buyers. Also, the seller or agent must give a copy of this report (and Professional Opinion for 1st time condo conversions) to the buyer prior to the signing of a Purchase Agreement, or as otherwise required in Minneapolis Ordinance Chapter 248 and/or 250.
4. This report covers only those items listed on the form. The evaluator is not required to ignite the heating plant, use a ladder to observe the condition of the roofing, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead paint, any airborne gasses (including radon), asbestos, wood stoves, fireplaces or air conditioners. Gas inserts in fireplaces WILL be evaluated.
5. This report is not an FHA, VA or Section 8 inspection. This report is not a code compliance inspection. It is not an appraisal. This report may be based upon different standards than the lender, FHA or VA.
6. The seller is required to provide the disclosure information in the box above. If this is not filled out, buyers are advised to request the seller to do so.
7. This report is valid for two years from the date of issue and only for the owner named on the report. It is required for all single-family homes, duplexes, townhouses or 1st time condominium conversions offered for sale.
8. **Any questions** regarding this report should be directed to the evaluator whose name and phone number appear below.
Any complaints regarding this report should be directed to Truth in Housing at (612) 673-5840, Minneapolis Inspections Division, 250 South 4th Street #300, Minneapolis, MN 55415.

I hereby certify that this report is made in compliance with the Minneapolis Code of Ordinances, Chapter 248, and that I utilized care and diligence reasonable and ordinary for one meeting the Certification Standards. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

Evaluator Name: Richard Olson

Phone: 952-920-1360

Evaluation Date: 9/12/2008

Signature: Richard Olson

Evaluation #: 20085646

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements **C** :=Comments **NA** :=Not Applicable/Does Not Apply **B** :=Below Minimum Requirements **SC** :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required **RRP** :=Repair/Replace, Permit/City Inspector Required **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Basement

1. Basement Stairs/Railings
 - B, Stairway headroom is less than 6' 8".
2. Basement Floors
 - M, Meets Minimum Requirements
3. Foundation Walls
 - C, Other Comment: - Covered
4. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
5. First Floor, Floor System
 - C, Other Comment: - Covered
6. Columns & Beams
 - C, Other Comment: - Covered
7. Basement Sleeping Rooms
 - NA, Not Applicable/Does Not Apply
8. Basement Plumbing Fixtures
 - M, Meets Minimum Requirements
9. Sump Pumps
 - NA, Not Applicable/Does Not Apply
10. Smoke Detectors / CO Detectors
 - M, Meets Minimum Requirements
11. Basement Electrical Outlets/Fixtures
 - B, Unprotected light (missing globe)
 - SC, Ungrounded 3-prong outlet.
 - B, Below Minimum Requirements: - Metal pull chain

Electric

Amps:100

Volts:220

12. Electrical service installation
 - M, Meets Minimum Requirements
13. Separate 20-amp Kitchen Circuit indexed at Service Panel
 - M, Meets Minimum Requirements
14. Separate 20-amp Laundry Circuit indexed at Service Panel
 - M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Plumbing

- 15. Floor Drains
M, Meets Minimum Requirements
- 16. Drain, Waste & Vent Piping
C, None visible.
- 17. Water Supply Piping
B, Below Minimum Requirements: - Some galvanized piping
- 18. Gas Piping
M, Meets Minimum Requirements
- 19. Copper Water Line Visible on the Street Side of Water Meter
M, Meets Minimum Requirements

Water heater

- 20. Water Heater & Installation
RRE, Water heater not operating due to water-shut off and/or is winterized. No other visible problems. Evaluator required to return after water service restored.
- 21. Water Heater Venting
B, Below Minimum Requirements: - Venting location
RRE, Repair/Replace: - Downward slope on vent

Heating

HeatingFuel:Gas

HeatingType:Forced air

- 22. Heating Plant Viewed in Operation
RRE, Heating plant not in operation. Reinspection required.
- 23. Heating Plant & Installation
M, Meets Minimum Requirements
- 24. Heating Plant Combustion Venting
M, Meets Minimum Requirements
- 25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures
NA, Not Applicable/Does Not Apply

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Laundry

26. Gas Piping

RRE, Uncapped gas line. A permit is not required to cap the gas line. Installation of a gas appliance requires a plumbing permit.

27. Dryer Venting

M, Meets Minimum Requirements

28. Plumbing Fixtures

RRE, Missing backflow preventer on laundry tub faucet threaded end.

Kitchen

29. Walls and Ceiling Components

M, Meets Minimum Requirements

30. Evidence of Dampness or Staining

M, Meets Minimum Requirements

31. Floor Condition

M, Meets Minimum Requirements

32. Window Size & Openable Area

M, Meets Minimum Requirements

33. Window & Door Condition/Mechanical Venting

M, Meets Minimum Requirements

34. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

35. Plumbing Fixtures

M, Meets Minimum Requirements

36. Water Flow

RRE, Unable to properly test, the water is shut off. Reinspection required.

37. Gas Piping

M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Dining Room/Living Room

- 38. Walls and Ceiling Components
M, Meets Minimum Requirements
- 39. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 40. Floor Area & Ceiling Height
M, Meets Minimum Requirements
- 41. Floor Condition
M, Meets Minimum Requirements
- 42. Window Size & Openable Area
M, Meets Minimum Requirements
- 43. Window & Door Condition
M, Meets Minimum Requirements
- 44. Electrical Outlets/Fixtures
M, Meets Minimum Requirements

Bathroom (Main bathroom)

- 45. Walls & Ceiling Components
M, Meets Minimum Requirements
- 46. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 47. Floor Condition
M, Meets Minimum Requirements
- 48. Window Size & Openable Area/Mechanical Vent
M, Meets Minimum Requirements
- 49. Window & Door Condition
M, Meets Minimum Requirements
- 50. Electrical Outlets & Fixtures
M, Meets Minimum Requirements
- 51. Plumbing Fixtures
RRE, Improper air gap on toilet ballcock.
- 52. Water Flow
RRE, Water off at time of evaluation. Re-inspection required.

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Bathroom (Basement bathroom)

- 45. Walls & Ceiling Components
M, Meets Minimum Requirements
- 46. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 47. Floor Condition
M, Meets Minimum Requirements
- 48. Window Size & Openable Area/Mechanical Vent
M, Meets Minimum Requirements
- 49. Window & Door Condition
M, Meets Minimum Requirements
- 50. Electrical Outlets & Fixtures
M, Meets Minimum Requirements
- 51. Plumbing Fixtures
RRE, Improper air gap on toilet ballcock.
- 52. Water Flow
RRE, Water off at time of evaluation. Re-inspection required.

Hallways/Stairwells

- 53. Walls and Ceiling Components
M, Meets Minimum Requirements
- 54. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 55. Floor Condition
M, Meets Minimum Requirements
- 56. Window & Door Condition
M, Meets Minimum Requirements
- 57. Electrical Outlets/Fixtures
M, Meets Minimum Requirements
- 58. Stairs and Railings
NA, Not Applicable/Does Not Apply
- 59. Smoke Detectors /CO Detectors
RRE, Missing smoke detector(s). - in hallway

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Bedroom (Two front bedrooms)

- 60. Walls and Ceiling Components
M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
M, Meets Minimum Requirements
- 63. Floor Condition
C, Not visible.
- 64. Window Size & Openable Area
M, Meets Minimum Requirements
- 65. Window & Door Condition
M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures
M, Meets Minimum Requirements

Bedroom (Rear bedroom)

- 60. Walls and Ceiling Components
M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
M, Meets Minimum Requirements
- 63. Floor Condition
C, Not visible.
- 64. Window Size & Openable Area
M, Meets Minimum Requirements
- 65. Window & Door Condition
M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures
M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Porch/Sunroom/Other

- 67. Walls and Ceiling Components
M, Meets Minimum Requirements
- 68. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 69. Floor Condition, Area & Ceiling Height
M, Meets Minimum Requirements
- 70. Window & Door Condition
M, Meets Minimum Requirements
- 71. Electrical Outlets/Fixtures
M, Meets Minimum Requirements

Attic Space

InsulationType:Cellulose

InsulationDepth:9-12

- 72. Roof Boards & Rafters / Ventilation
M, Meets Minimum Requirements
- 73. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 74. Electrical Outlets & Fixtures
NA, Not Applicable/Does Not Apply
- 75. Mechanical Venting
M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Exterior

- 76. Foundation
 - M, Meets Minimum Requirements
- 77. Basement Windows
 - M, Meets Minimum Requirements
- 78. Drainage (Grade) / Rainleaders
 - M, Meets Minimum Requirements
- 79. Exterior Walls
 - M, Meets Minimum Requirements
- 80. Doors (frames/storms/screens/deadbolt locks)
 - M, Meets Minimum Requirements
- 81. Windows (frames/storms/screens)
 - M, Meets Minimum Requirements
- 82. Stoops
 - M, Meets Minimum Requirements
- 83. Cornice & Trim
 - M, Meets Minimum Requirements
- 84. Roof Covering & Flashing
 - M, Meets Minimum Requirements
- 85. Chimney
 - M, Meets Minimum Requirements
- 86. Electrical Outlets/Fixtures
 - M, Meets Minimum Requirements
- 87. Exterior Plumbing-Backflow Prevention
 - RRE, Missing backflow preventers on exterior faucets (sillcocks). - two locations
- 88. Two-Family Dwelling Egress
 - NA, Not Applicable/Does Not Apply

Open/Unheated Porch

Not Applicable

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Garage

- 94. Roof Structure & Covering
 - M, Meets Minimum Requirements
- 95. Wall Structure & Covering
 - M, Meets Minimum Requirements
- 96. Garage Doors
 - B, No closer on service door.
- 97. Automatic Garage Door Opener
 - M, Meets Minimum Requirements
- 98. Electrical Outlets/Fixtures
 - SC, Missing cover plate(s).
 - RRE, Repair/Replace: - Open junction boxes

Miscellaneous

- 99. Clutter/Sanitation/Vermin
 - M, Meets Minimum Requirements
- 100. Other
 - C, Other Comment: - THE CITY INSPECTION IS A LIMITED INSPECTION. FOR A MORE COMPREHENSIVE INSPECTION (BUYER'S INSPECTION) CALL AN INSPECTOR TO SCHEDULE AN INSPECTION.
 - RRE, Repair/Replace: - RE-INSPECTION REQUIRED BY SAME EVALUATOR TO REMOVE CERTIFICATIONS AND NON-PERMITTED ITEMS. ADDITIONAL FEE WILL BE NECESSARY FOR RE-INSPECTION. CALL RICHARD OLSON AT 952-920-1360 TO SCHEDULE INSPECTION

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



Truth in Housing Repair Notification

City of Minneapolis-Inspections Division

Truth in Sale of Housing, 250 South 4th Street, Room 300

Minneapolis, MN 55415

Issued To:

9/16/2008

Branko Kastratovich
6528 Sherwood Ave.
Edina, MN 55435

Owner does not have to complete repairs if the house is not sold.

Pursuant to Minneapolis Code of Ordinances, Sections 248.20 and 248.225, the owner may make the repairs. If the owner makes the repairs, a Certificate of Approval (needed for closing) will be issued after the repairs have been inspected and approved. The owner does not have to complete the repairs if the house does not sell. If the owner does not make the repairs, the buyer must sign an acknowledgement of responsibility form (provided by the City) and return it to the City. The buyer has 90 days from closing to complete the repairs. Your prompt cooperation in attending to the repair items is appreciated however, failure to comply by these deadlines may result in legal action.

REQUIRED REPAIRS

ID	Description	Area	Comment
20	Water Heater & Installation	Water heater	Water heater not operating due to water-shut off and/or is winterized. No other visible problems. Evaluator required to return after water service restored.
21	Water Heater Venting	Water heater	Repair/Replace: - Downward slope on vent
22	Heating Plant Viewed in Operation	Heating	Heating plant not in operation. Reinspection required.
26	Gas Piping	Laundry	Uncapped gas line. A permit is not required to cap the gas line. Installation of a gas appliance requires a plumbing permit.
28	Plumbing Fixtures	Laundry	Missing backflow preventer on laundry tub faucet threaded end.
36	Water Flow	Kitchen	Unable to properly test, the water is shut off. Reinspection required.
51	Plumbing Fixtures	Bathroom(Main bathroom)	Improper air gap on toilet ballcock.
52	Water Flow	Bathroom(Main bathroom)	Water off at time of evaluation. Re-inspection required.
51	Plumbing Fixtures	Bathroom(Basement bathroom)	Improper air gap on toilet ballcock.
52	Water Flow	Bathroom(Basement bathroom)	Water off at time of evaluation. Re-inspection required.
59	Smoke Detectors /CO Detectors	Hallways/Stairwells	Missing smoke detector(s) - in hallway
87	Exterior Plumbing-Backflow Prevention	Exterior	Missing backflow preventers on exterior faucets (sillcocks) - two locations
98	Electrical Outlets/Fixtures	Garage	Repair/Replace: - Open junction boxes
100	Other	Miscellaneous	Repair/Replace: - RE-INSPECTION REQUIRED BY SAME EVALUATOR TO REMOVE CERTIFICATIONS AND NON-PERMITTED ITEMS. ADDITIONAL FEE WILL BE NECESSARY FOR RE-INSPECTION. CALL RICHARD OLSON AT 952-920-1360 TO SCHEDULE INSPECTION

SAFETY CHECKS

The systems listed below must be checked by a licensed contractor. The contractor must be licensed by the City of Minneapolis and/or the State of Minnesota in that specific trade to check the work. Return safety check forms to the address above or fax to (612) 673-2437. If "Evaluator Return" is indicated below, the evaluator may return to view the system that was not in operation at the time of

Truth in Sale of Housing Disclosure Report

Address: 5374 Shoreview Ave Minneapolis, MN



the initial evaluation. The evaluator may find additional work is needed on the system.

If the system was repaired or replaced, only a licensed contractor (not the evaluator) can do the safety check. Permits may be needed.

NONE

PERMIT REQUIRED REPAIR

The permit must be pulled before scheduling. Call the inspector listed on the permit to set an appointment. You need to have the permit number to set the appointment. There will be a charge for the permit, which covers the inspection.

NONE

Reinspection Process

When all the items are completed they must be inspected and approved.

For items that need a permit:

If your notification indicates PERMIT NEEDED, the permit(s) must be pulled and work completed BEFORE the re-inspection takes place. If you are a homeowner occupant of a single family house, you may obtain a permit, if you are not, you must hire a licensed contractor. Bring this notification with you when you apply for permits.

For items that do not need a permit:

Call the evaluator who did the initial TISH report to re-inspect all the non-permit items. The evaluator's name and phone number are on the bottom of page 1 of the report. There will be a charge for this inspection.

Appeal

This repair notice may be appealed. Section 248.150 of the Minneapolis Code of Ordinances provides that an appeal must be filed in writing within thirty (30) days of the date of this notice accompanied with a \$100 filing fee. If you wish to appeal this order, call (612) 673-5840 for an application.

Assistance

If you need financial assistance to complete these repairs, you may call the Greater Metropolitan Housing Corporation (GMHC) at 612-378-7985.